

Date: Monday, 09/02/2009 7:14:52 AM
User: Linda Lacelle

Process Sheet

| | | | |
|------------------------------------|-------------------------------------|---------------------------|---------------|
| Customer : | CU-DAR001 Dart Helicopters Services | Drawing Name : | WEAR SHOE KIT |
| Job Number : | 45599 | | |
| Estimate Number : | 12939 | | |
| P.O. Number : | | Part Number : | DSI9372011 |
| This Issue : | 09/02/2009 | S.O. No. : | |
| Prsht Rev. : | NC | Drawing Number : | DSI9372 REV A |
| First Issue : | / / | Project Number : | N/A |
| Previous Run : | 42129 | Drawing Revision : | A |
| | Type : | Material : | |
| | SMALL /MED FAB | Due Date : | 09/02/2009 |
| Written By : | | Qty: | 1 |
| Checked & Approved By : | | Um: | Each |
| Comment : | EsRev:A New Issue 07-07-09 JLM | | |

Additional Product

Job Number:



| | | |
|----------------|------------------------------|----------------------|
| Seq. #: | Machine Or Operation: | Description : |
|----------------|------------------------------|----------------------|

| | | |
|-----|----|------------------|
| 1.0 | DC | DOCUMENT CONTROL |
|-----|----|------------------|



Comment: DOCUMENT CONTROL

Photocopy bluefile & type labels per PPPDSI9372-011 CHG001

| | | |
|-----|-------------|-----------------------|
| 2.0 | PACKAGING 1 | PACKAGING RESOURCE #1 |
|-----|-------------|-----------------------|



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

| | | |
|-----|--------|----------|
| 3.0 | D35645 | Wearshoe |
|-----|--------|----------|



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WEARSHOE

Batch: 43893

| | | |
|-----|--------|----------|
| 4.0 | D35649 | Wearshoe |
|-----|--------|----------|



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WEARSHOE

Batch: 44172

| | | |
|-----|---------|----------|
| 5.0 | D356411 | Wearshoe |
|-----|---------|----------|



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WEARSHOE

Batch: 44656

Date: Monday, 09/02/2009 7:14:52 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEAR SHOE KIT

Job Number: 45599

Part Number: DS19372011

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

D356413

Wearshoe



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WEARSHOE

Batch: 44657

SC

7.0

D35661

Gasket



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

GASKET

Batch: B44173

SC

8.0

D35665

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

GASKET

Batch: B44174

SC

9.0

D356613

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

GASKET

Batch: B44008

SC

10.0

AN3C4A

BOLT



Comment: Qty.: 50.0000 Each(s)/Unit Total : 50.0000 Each(s)

BOLT

Batch: M110139

M110468

SC

11.0

AN960C10L

washer



Comment: Qty.: 50.0000 Each(s)/Unit Total : 50.0000 Each(s)

washer

M109061

SC

12.0

ALS41032130

Insert



Comment: Qty.: 6.0000 Each(s)/Unit Total : 6.0000 Each(s)

Insert

Batch: M105819

9/2/9

SC

Date: Monday, 09/02/2009 7:14:52 AM
User: Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEAR SHOE KIT

Job Number: 45599

Part Number: DSI9372011

Job Number:



Seq. #:

Machine Or Operation:

Description :

13.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

5/09/02/09 (H)

14.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP DSI9372-011

Location: _____

PPP Rev: _____

Draft

8/09/02/09 (H)

15.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

09/02/09 (H)

Job Completion



MF 09-02-09